



Export **MEDIT** STL Files


1. Click the "Export 3D data" button



2. Select a folder location to save the file on the local PC. You can select the file type between .stl, .obj, and .ply.



3. Select an option in the "Complete" dialog to export the scan data to the selected location after processing.



4. Select "Open" to go directly to the folder directory.

